# S E R V I C E N O T E

SUPERSEDES: None

## **54754A TDR Module**

**Serial Numbers:** 0000A00000 / 9999Z99999

# 54754A TDR Module fails vertical cal. in 54750A/83480A after use in 86100A

**Duplicate Service Notes:** 54753-02

#### **Situation:**

A 54754A TDR module that is used in an 86100A Infiniium DCA will fail vertical calibration if used again in either an 83480A or 54750A mainframe.

#### **Solution / Action:**

This problem has been solved in a new firmware version A.07.12 for both the 83480A and the 54750A. The new firmware can be obtained at:

http://lwd.marketing.agilent.com/Service&Support/Firmware/54750/agilent\_54750\_software.htm

-or-

http://lwd.marketing.agilent.com/Service&Support/Firmware/83480A/agilent\_83480a\_software.htm

View the readme files at these sites for more information on the files.

DATE: June 2001

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICAT	TION:	
	INFORMATI	ON ONLY
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
RC	5360	

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

