

5517B/C/D-03

S E R V I C E N O T E

SUPERSEDES: None

**5517A/B/C Laser Head**

**Serial Numbers:** 0000A00000 / 9999A99999

**Replace fast-blow fuses with slow-blow fuses**

**To Be Performed By:** HP-Qualified Personnel

**Parts Required:** P/N 2110-0318

**Situation:**  
The fast-blow fuse needs to be replaced by slow-blow fuse for the 05517-68004 board of the Product 5517B/C/D.

**Service Strategy:**  
When dealing with 05517-68004 board returns, it is necessary to replace fast-blow fuse P/N 2110-0027 to slow-blow fuse P/N 2110-0318.

**Description:**  
The current spec for P/N 2110-0027 is .12A. The current spec for P/N 2110-0318 is .125A.

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>MODIFICATION AVAILABLE</b>		
ACTION CATEGORY:	<b>AGREEABLE TIME</b>	<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	AVAILABLE UNTIL: Product's Support Life
AUTHOR: EL	ENTITY: 0200	ADDITIONAL INFORMATION:

