

S E R V I C E N O T E

SUPERSEDES: None

5DX Series II Structural Process Test System**Situation:**

The cooling fan for the micron CPU is failing. This causes a possible CPU failure due to overheating. The reliability of the fan is being investigated.

Solution:

Replace the defective fan with HP part number 5041-6262. The fan is mounted inside a plastic fan guard. The fan guard is mounted on the rear panel of the CPU enclosure. Remove the defective fan from the guard and insert the replacement.

DATE: June 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

KDP

ENTITY:

0980

ADDITIONAL INFORMATION:

