

## S E R V I C E N O T E

SUPERSEDES: None

**6030A Autoranging System DC Power Supply**

Serial Number: 0000A00000 / 9999A99999

**GPIB Interface Assembly Availability****Duplicate Service Notes:**

6030A-20  
 6031A-22  
 6032A-21  
 6033A-13  
 6035A-10  
 6038A-11

**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

06031-61006 DFI/RI/Relay Link Tested GPIB Interface Assembly  
 06031-61007 Option 700 CIIL Tested GPIB Interface Assembly  
 5063-3465 Tested GPIB Interface Assembly

**Situation:**

The GPIB Listener / Talker chip used in the manufacture of tested GPIB assemblies 06031-61004, 06031-61006 and 06031-61007 is no longer available therefore these assemblies can no longer be manufactured.

*Continued*

DATE: December 2000

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**AUTHOR:  
CP/BHENTITY:  
2100

ADDITIONAL INFORMATION:



**Solution / Action:**

For models with a single A8 GPIB Interface Assembly:

Replace defective GPIB Interface assembly part number 5060-3359, 5063-2308 or 5063-3465 with GPIB assembly 5063-3465.

Send the defective 5060-3359, 5063-2308 or 5063-3465 to the Power Products Div.

For models with the dual A7 & A8 GPIB Interface assembly:

Replace defective GPIB Interface assembly part numbers 06031-61004 or 06031-61006 with restored GPIB assembly 06031-61006.

Send the defective GPIB assembly to Power Products Div for refurbishing.

For models with an A8 GPIB CIIL option 06031-61007 Interface assembly:

This interface assembly can only be replaced with a 06031-61007 assembly. Replace the defective GPIB assembly with a restored 06031-61007 assembly.

Send the defective 06031-61007 to Power Products Div. for refurbishing. If a restored 06031-61007 is not available contact the Power Products Div. to determine who will perform a component level repair on the defective assembly.