

S E R V I C E N O T E

SUPERSEDES: None

6038A Autoranging System DC Power Supply

Serial Number: 0000A00000 / 9999A99999

GPIB Interface Assembly Availability

Duplicate Service Notes:

- 6030A-20
- 6031A-22
- 6032A-21
- 6033A-13
- 6035A-10
- 6038A-11

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

- 06031-61006 DFI/RI/Relay Link Tested GPIB Interface Assembly
- 06031-61007 Option 700 CIIL Tested GPIB Interface Assembly
- 5063-3465 Tested GPIB Interface Assembly

Situation:

The GPIB Listener / Talker chip used in the manufacture of tested GPIB assemblies 06031-61004, 06031-61006 and 06031-61007 is no longer available therefore these assemblies can no longer be manufactured.

Continued

DATE: December 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: CP/BH	ENTITY: 2100	ADDITIONAL INFORMATION:



Solution / Action:

For models with a single A8 GPIB Interface Assembly:

Replace defective GPIB Interface assembly part number 5060-3359, 5063-2308 or 5063-3465 with GPIB assembly 5063-3465.

Send the defective 5060-3359, 5063-2308 or 5063-3465 to the Power Products Div.

For models with the dual A7 & A8 GPIB Interface assembly:

Replace defective GPIB Interface assembly part numbers 06031-61004 or 06031-61006 with restored GPIB assembly 06031-61006.

Send the defective GPIB assembly to Power Products Div for refurbishing.

For models with an A8 GPIB CIIL option 06031-61007 Interface assembly:

This interface assembly can only be replaced with a 06031-61007 assembly. Replace the defective GPIB assembly with a restored 06031-61007 assembly.

Send the defective 06031-61007 to Power Products Div. for refurbishing. If a restored 06031-61007 is not available contact the Power Products Div. to determine who will perform a component level repair on the defective assembly.