									654	4A-0	2A
S	Е	R	V	Ι	С	Е		Ν	0	Т	Е
							SUPEF	SEDE	S: 6544	A-02	
654	4A 200	W Gei	neral P	urpos	se Pow	er Sup	oply				
Seria	al Numb	er: See b	elow								
Inte	rmitten	t Phon	e Cable	<del>)</del> S							
Dup	licate Se	rvice No	tes:								
6541	A-02A	US36	360146 /	US363(	60165						
542	A-02A	US36360286 / US36360315									
5543	A-02A	US36340266 / US36340336									
5544	A-02A	US36390176 / US36390211									
5545	A-03A	US36340126 / US36340141									
641	A-03A	US36410246 / US36410290									
5642	A-03A	US36400586 / US36400776									
6643	A-03A	US364	400711 /	US364(	00830						
6644	A-03A	US364	410441 /	US364	10576						
6645	A-04A	US363	390351 /	US3639	90451						
To B	e Perfor	med By:	Agilent-	Qualifi	ed Person	nnel					
Part	s Requir	ed:									
	2-80011 2-80010										
										Continue	ed.
							DATE:	Febru	ary 2001		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:								
MODIFICATION RECOMMENDED								
ACTION CATEGORY:	<ul> <li>IMMEDIATELY</li> <li>ON SPECIFIED FAILURE</li> <li>AGREEABLE TIME</li> </ul>	STANDARDS: LABOR 0.5 Hours						
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT						
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Product Support Life						
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION: This is a multi Model No. Service Note						

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



## Situation:

The 2 phone style cables might have been improperly crimped causing intermittent connections on the cables. Could cause "Secondary Down" or "Serial Down" message.

## Solution / Action:

Units returned for any reason in the specified serial number range exhibiting "Secondary" or "Serial Down" messages or intermittent communication problems. Replace the gray phone style cables.