

S E R V I C E N O T E

SUPERSEDES: NONE

6575A DC Power Supply**Serial Numbers:** 0000A00000 / 3423A00208**Downprogramming FETs Q901 and Q902 no longer have an isolated package.****Duplicate Service Notes:**

6573A-01 Serials: 0000A00000 / 3432A00187
 6574A-01 Serials: 0000A00000 / 3432A00258
 6575A-01 Serials: 0000A00000 / 3432A00208
 6673A-03 Serials: 0000A00000 / 3501A00796
 6674A-03 Serials: 0000A00000 / 3501A00941
 6675A-04 Serials: 0000A00000 / 3502A00551
 6682A-01 Serials: 0000A00000 / 3514A00168
 6683A-01 Serials: 0000A00000 / 3514A00178
 6684A-01 Serials: 0000A00000 / 3514A00188

To Be Performed By: Agilent-Qualified Personnel**Parts Required:** Kit, Dwnprgmr-Svc, 5063-3403 (1 kit per FET)*Continued*

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DF	ENTITY: 2100	ADDITIONAL INFORMATION:
-------------------	---------------------	-------------------------

Situation:

The original part, part number 1855-0835 has been discontinued by the manufacturer and the replacement part does not have an isolated package. Therefore, it cannot be mounted directly to the heat sink.

Solution/Action:

If the original part fails it may be replaced by the service kit 5063-3403. The kit consists of a new FET, 1855-1003, and an insulator, 0340-1507.