

S E R V I C E N O T E

SUPERSEDES: None

**66102A System DC Power Supply**

**Serial Numbers:** 3139A00101 / 3226A00420

**Output connector cover assemblies crack**

**Duplicate Service Notes:**

- 66101A-01
- 66102A-01
- 66103A-01
- 66104A-01
- 66105A-01
- 66106A-01

**To Be Performed By:** Agilent-Qualified Personnel or Customer

**Parts Required:**

P/N	Description
5040-1682	Bottom Cover assembly
5040-1683	Top cover assembly

**Situation:**

The DC Power Module output connector covers crack near the screw holes.

*Continued*

DATE: 19 January 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 0.5 Hours			
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: December 1995		
AUTHOR: DF	ENTITY: 2100	ADDITIONAL INFORMATION:			

**Solution/Action:**

New cover assemblies are available. The new cover assemblies have been modified to strengthen the areas most likely to be stressed during installation. Screws should be evenly hand-tightened only and the use of thread locking adhesives should be avoided.