

S E R V I C E N O T E

SUPERSEDES: None

6624A Multiple Output Linear System Power Supply

Serial Numbers: See below

Installing New Fan

Duplicate Service Notes:

| | |
|----------------------------------|----------------------------------|
| 6621A-12 0000A00000 / US37370201 | 6626A-09 0000A00000 / US37370246 |
| 6622A-10 0000A00000 / US37360151 | 6627A-05 0000A00000 / US37350211 |
| 6623A-14 0000A00000 / US37360171 | 6628A-09 0000A00000 / US37380111 |
| 6624A-11 0000A00000 / US37350501 | 6629A-09 0000A00000 / US37380111 |
| 6625A-09 0000A00000 / US37380136 | |

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

5063-4895 Service Kit, consisting of fan (p/n 3160-0899), and cable (p/n 8120-8730).

Situation:

Old fan p/n 3160-0097 is being replaced by p/n 3160-0899, old style cable p/n 5060-3443 is not compatible with new fan. New cable number is 8120-8730, both are in the service kit. Above serial numbers and greater have new fan assemblies.

Solution / Action:

Order Service Kit 5063-4895 when replacing old style fan, (p/n 3160-0097). Make sure direction of air flow is going into the unit.

DATE: August 1998

ADMINISTRATIVE INFORMATION

| | | |
|------------------------------|---------|---|
| SERVICE NOTE CLASSIFICATION: | | |
| INFORMATION ONLY | | |
| AUTHOR: | ENTITY: | ADDITIONAL INFORMATION: |
| BM | 2100 | Make sure direction of air flow from the fan is going into the unit |