

S E R V I C E N O T E

SUPERSEDES: None

6629A Multiple Output Linear System Power Supply

Serial Numbers: See below

Installing New Fan

Duplicate Service Notes:

6621A-12 0000A00000 / US37370201	6626A-09 0000A00000 / US37370246
6622A-10 0000A00000 / US37360151	6627A-05 0000A00000 / US37350211
6623A-14 0000A00000 / US37360171	6628A-09 0000A00000 / US37380111
6624A-11 0000A00000 / US37350501	6629A-09 0000A00000 / US37380111
6625A-09 0000A00000 / US37380136	

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

5063-4895 Service Kit, consisting of fan (p/n 3160-0899), and cable (p/n 8120-8730).

Situation:

Old fan p/n 3160-0097 is being replaced by p/n 3160-0899, old style cable p/n 5060-3443 is not compatible with new fan. New cable number is 8120-8730, both are in the service kit. Above serial numbers and greater have new fan assemblies.

Solution / Action:

Order Service Kit 5063-4895 when replacing old style fan, (p/n 3160-0097). Make sure direction of air flow is going into the unit.

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
BM	2100	Make sure direction of air flow from the fan is going into the unit