6632B-01

SUPERSEDES: NONE

6632B DC Source

Serial Numbers: See Below

Low range current readback out of spec.

Duplicate Service Notes:

66332A-01 Serial Numbers: US36320632 / US36320653 66312A-01 Serial Numbers: US36312080 / US37442212 6612B-01 Serial Numbers: US36340716 / US36340740 6632B-01 Serial Numbers: US36351903 / US36351964 6633B-01 Serial Numbers: US36390490 / US36390503 6634B-01 Serial Numbers: US36380375 / US36380389

To Be Performed By: Agilent-Qualified Personnel

Situation:

Units between the given serial number range might have had their low current range readback mis calibrated.

Solution / Action:

Should any units be returned with a current readback problem, recalibrate the low range current readback as described in the service manual.

DATE: December 1997

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | |
|------------------------------|---|---|
| MODIFICATION RECOMMENDED | | |
| ACTION CATEGORY: | ☐ IMMEDIATELY ■ ON SPECIFIED FAILURE □ AGREEABLE TIME | STANDARDS: LABOR 1.0 Hours |
| LOCATION CATEGORY: | CUSTOMER INSTALLABLE | SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | AGILENT RESPONSIBLE UNTIL: December 2001 |
| AUTHOR: BM | ENTITY: 2100 | ADDITIONAL INFORMATION: |

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

