S E R V I C E N O T E

SUPERSEDES: NONE

66332A DC Source

Serial Numbers: See Below

Low range current readback out of spec.

Duplicate Service Notes:

66312A-01 Serial Numbers: US36312080 / US37442212 66332A-01 Serial Numbers: US36320632 / US36320653 6612B-01 Serial Numbers: US36340716 / US36340740 6632B-01 Serial Numbers: US36351903 / US36351964 6633B-01 Serial Numbers: US36390490 / US36390503 6634B-01 Serial Numbers: US36380375 / US36380389 6634B-01 Serial Numbers: US36380376 / US36380389

To Be Performed By: Agilent-Qualified Personnel

Situation:

Units between the given serial number range might have had their low current range readback mis calibrated.

Solution / Action:

Should any units be returned with a current readback problem, recalibrate the low range current readback as described in the service manual.

DATE: December 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: December 2001
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION:

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

