S E R V I C E N O T E

SUPERSEDES: 6642A-03

6642A 200W General Purpose Power Supply

Serial Number: See below

Intermittent Phone Cables

Duplicate Service Notes:

6541A-02A	US36360146 / US36360165
6542A-02A	US36360286 / US36360315
6543A-02A	US36340266 / US36340336
6544A-02A	US36390176 / US36390211
6545A-03A	US36340126 / US36340141
6641A-03A	US36410246 / US36410290
6642A-03A	US36400586 / US36400776
6643A-03A	US36400711 / US36400830
6644A-03A	US36410441 / US36410576
6645A-04A	US36390351 / US36390451

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

06652-80011 (W10, p/n 06652-80011) 06652-80010 (W9, p/n 06652-80010)

Continued

DATE: February 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
MODIFICATION RECOMMENDED							
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours					
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE INVENTORY:	☐ RETURN ■ SCRAP ☐ SEE TEXT	USED PARTS:	☐ RETURN ■ SCRAP ☐ SEE TEXT		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Product Support Life					
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION: This is a multi Model No.					

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

The 2 phone style cables might have been improperly crimped causing intermittent connections on the cables. Could cause "Secondary Down" or "Serial Down" message.

Solution / Action:

Units returned for any reason in the specified serial number range exhibiting "Secondary" or "Serial Down" messages or intermittent communication problems. Replace the gray phone style cables.