									66	653A-	-05
S	Е	R	V	Ι	С	Е		Ν	0	Т	Е
							SUPEF	RSEDES	B: NOM	NE	
665	53A 50	0W Ge	neral F	urpo	se Pow	er Sup	oply				
Seri	ial Numb	er: See b	elow								
Inte	ermitter	nt Phon	e Cable	es.							
Dup	olicate Se	ervice No	tes:								
655	1A-02	US36	480196 /	US364	80220						
	2A-02		230481 /								
655	3A-02	US36	340231 /	US3634	40289						
655	4A-02	US36	340261 /	US3634	40311						
655	5A-02	US36	340161 /	US3634	40171						
665	1A-05		400356 /								
	2A-05		400331 /								
	3A-05		400756 /								
	4A-05		390516 /								
665.	5A-05	US36	390401 /	US3639	90716						
To	Be Perfo	rmed By	: Agilent-	Qualifi	ed Person	nnel					
Par	ts Requi	red:									
		Part desig Part desig									
200	(1			,- <u>-</u>		- /				Continue	ed
							DATE:	Augus	t 1999		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:								
MODIFICATION RECOMMENDED								
ACTION CATEGORY:	<ul> <li>IMMEDIATELY</li> <li>ON SPECIFIED FAILURE</li> <li>AGREEABLE TIME</li> </ul>	STANDARDS: LABOR 0.5 Hours						
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE       □       RETURN       USED       □       RETURN         INVENTORY:       ■       SCRAP       PARTS:       ■       SCRAP         □       SEE TEXT       □       SEE TEXT						
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Product Support Lif						
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION: This is a multi Model No. Servic Note						

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



## Situation:

The 2 phone style cables might have been improperly crimped causing intermittent connections on the cables. Could cause "Secondary Down" or "Serial Down" message.

## Solution / Action:

Units returned for any reason in the specified serial number range exhibiting "Secondary" or "Serial Down" messages or intermittent communication problems. Replace the gray phone style cables.