6653A-11A-S

Implemented During Normal Course of Providing Support

> Supersedes: 6653A-11

6653A 500 Watt System Power Supply, 35V, 15A

Safety Service Note

Serial Numbers: MY40001943, MY40002285, MY40002303, MY40002357, MY40002361, MY40002372, MY40002381, MY40003279, MY40003335, MY53000128, MY53000129, MY53000145, MY53000301 only

POSSIBLE "SHOCK" HAZARD

WARNING HAZARD CLASS #2

The Problem – Regulatory noncompliance with the option 901 (Power cord for Australia / New Zealand)

Parts Required:

P/N Description Qty.

8120-4419

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.1 Hours
LOCATION CATEGORY:	[X] CUSTOMER INSTALLABLE[]] ON-SITE (active On-site contract required)[X] SERVICE CENTER[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [X] SCRAP PARTS: [X] SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY: ALWAYS		NO CHARGE AVAILABLE UNTIL: EOS
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: SJ

ADDITIONAL INFORMATION:



Situation:

The Australian/New Zealand Regulations requires the use of power cord sets that meet AS3112. Since 2005, the live and neutral pins must be insulated for a prescribed length of pin. It was found that Keysight Technologies had shipped some power cord sets with the older style plug. To address this non-compliance, Keysight Technologies will supply a new power cord (part number 8120-4419) to affected customers.

Solution/Action:

- 1. Verify that your instrument(s) corresponds to the above model and serial numbers.
- 2. Replace the original power cord with the new power cord supplied by Keysight Technologies.
- 3. Destroy the original power cord to prevent it from being used with any electrical equipment, and recycle responsibly.

Revision History:

	ote Aut evision	hor R	Reason for Change
07 June 2016 01	SJ	A	As Published
12 May 2017 02	HY	R	Revised with the affected serial number(s) only