S E R V I C E N O T E

SUPERSEDES: None

6811A AC Source / Analyzer

Serial Number:

0000A00000/9999A99999 US00000000/US9999999

Replacing the Discontinued A8 DSP Assembly Part Number 5063-2315 (PCA-DSP,TSTD)

Duplicate Service Notes:

6811A-04

6812A-10

6813A-12

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

A8 Digital Signal Processing Assembly p/n 5063-2367 A2 GPIB Assembly p/n 5063-2376

Situation:

A8 Digital Signal Processing Assembly (DSP), part number 5063-2315, is no longer avaiable.

Continued

DATE: August 2001

ADMINISTRATIVE INFORMATION

INFORMATION ONLY		
AUTHOR: PS	ENTITY: 2100	ADDITIONAL INFORMATION:

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 6811A-04

Solution / Action:

If the A8 DSP Assembly, part number 5063-2315, (marked 5063-2323 for manufacturing purposes) requires replacment, order newer type A8 DSP, part number 5063-2367 and newer type A2 GPIB Assembly, part number 5063-2376.

Follow the service manual to replace these assemblies and re-initialize the unit as the applicable "B" model.

Example: initialize a 6811A as a 6811B. (Note: the ac source will now have the features of the "B" model. As of the date below, the firmware revision of the DSP is A.00.08)

Calibrate and performance test the AC source.

21/Aug/2001