S E R V I C E N O T E

SUPERSEDES: None

HP 70322A Synthesized Signal Generator

Serial Numbers: 0000A00000 / 2946A00187

I/O Assembly Replacement requires modification to Reference Assembly

Duplicate Service Notes:

8664A-01

8665A-02

8665B-01

Situation:

When an I/O assembly (08665-69104 or 08665-60204) is replaced in instruments (serial numbers noted above) a component on the Reference assembly (HP P/N 08665-61006) must be removed to insure proper operation of the reference oscillator.

NOTE: Billings related to replacement of the I/O or Reference assemblies are not covered by this Service Note.

Solution/Action:

Remove L307 on the Reference assembly. Refer to Figure 1 for component location. Re-calibration is not required.

Continued

DATE: 09 October 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hour
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ HP LOCATION	SERVICE ☐ RETURN USED ☐ RETURN INVENTORY: ■ SCRAP PARTS: ■ SCRAP SEE TEXT ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	RESPONSIBLE UNTIL: 01 November 1997
AUTHOR: LHL	ENTITY: 1000	ADDITIONAL INFORMATION:

© 1992 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 SERVICE NOTE 70322A-01

