

S E R V I C E N O T E

SUPERSEDES: None

70900A Local Oscillator**Serial Numbers:** 0000A00000 / 3049A02763**A2 Video Board Compatibility****Parts Required:** None**Situation:**

The 70900-60168 Video Board isn't compatible with older revisions of 70900A/B firmware. The 70900A/B must have a firmware revision of 910802 or later to support the 70900-60168 assembly. This firmware corresponds to a Version Update Fix (V.U.F) of B.04.00 or later.

Solution/Action:

This applies to 70900Bs with a serial number less than 3222A01410 and all of the 70900As shipped with the 70900-60094 Video Board. The 70900-60094 and the 70900-69094 exchange assembly may still be ordered. The 70900-60168 may be used in either the 70900A or the 70900B if they have a firmware revision of 910802 or later.

DATE: 18 May 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

RDS

ENTITY:

4500

ADDITIONAL INFORMATION: