81150A-02

<u>SERVICE NOTE</u>

Supersedes: NONE

81150A Pulse Function Arbitrary Noise Generator

Serial Numbers: ALL

Instrument refuses to boot if the duration of a power fail was less than 3 seconds. The unit shows a black display.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: HK	PRODUCT LINE: PL24
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



October 6, 2008

Page 1 of 2

Page 2 of 2 81150A-02

Situation:

Assume there is a power fail, i.e. power was disconnected or interrupted for less than 3 seconds from the 81150A and power comes back within these 3 seconds, then the 81150A will not boot correctly and the front panel display will remain black.

Solution/Action:

Disconnect the power cable from the 81150A for at least 30 seconds.

Then re-connect the power cable to the unit and press the power on button to boot the unit.

The 81150A should now boot without any problems.

If you have any questions contact:

bvs-pdga_support@agilent.com