

S E R V I C E N O T E

SUPERSEDES: None

83215A RF Interface**Serial Numbers:** 0000A00000 / JP2KA00301**Duplicate Service Notes:** 83215B-03**Incorrect relay may be installed****To Be Performed By:** HP-qualified personnel**Situation:**

Incorrect relay may be installed in the instrument serialized above. It will not affect any instrument performance.

Wrong part number HP 8765A OPT 015,100**Correct part number** HP 8765B OPT 015,100**Solution/Action:**

None

DATE: March 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

YO

ENTITY:

3355

ADDITIONAL INFORMATION: