

S E R V I C E N O T E

SUPERSEDES: None

8482B High-power sensor, 100 kHz to 4.2 GHz**Caution label replacement instructions for the 8482B****To Be Performed By:** Agilent-Qualified Personnel or customer**Parts Required:**

P/N	Description	Quantity
08486-80005	Label, Info	1
08482-80003	Label, ID	1

Situation:

The 08481-80006 Caution Label has been obsoleted by ECO #53-14813, and replaced by the 08486-80005 Info Label. The caution information relating to maximum power, ESD and matching pad has been transferred to the 08482-80003 Product ID Label.

8482B sensors produced before ECO 53-14813 implementation are affected. If the 08481-80006 Caution label requires replacement (with the 08486-80005), the Product ID label must also be replaced so the caution information remains readily available to the user.

Solution / Action:

When replacing an 08481-80006 label with an 08486-80005, the Product ID label should also be replaced for 8482B models if caution information relating to maximum power, ESD and matching pad are no longer present anywhere on the sensor. For the 8482B, replace both 08486-80005 and 08482-80003.

DATE: November 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLYAUTHOR:
TMENTITY:
5390

ADDITIONAL INFORMATION:

