

S E R V I C E N O T E

SUPERSEDES: None

85462A EMC Receiver RF Section

Serial Numbers: 0000A00000 / 9999Z99999

EEROM Firmware Upgrade

Duplicate Service Notes: 85422E-01, 85462A-01

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Qty.	Description
5063-1621	1	Firmware Kit
5962-5084	1	Reference Manual

Situation:

Replacement firmware provides the following:

- 1) Improvement of the internal CAL routine for 9 kHz CISPR IFBW,
- 2) Changes 1 MHz 3 dB IFBW to 1 MHz 6 dB IFBW,
- 3) Adds LOG sweep capability, and
- 4) fixes several "minor bugs"

Solution/Action:

At the customer's convenience or when returned to the CSC for repair or calibration, if the firmware revision date is not Rev 94.09.08, then order kit 5063-1621. Also order new Reference Manual, 5962-5084 if replacing firmware version Rev 94.02.02.

DATE: December 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☒ AGREEABLE TIME	STANDARDS: Labor 0.5 Hour	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: December 1997
AUTHOR: SPB	ENTITY: 5340	ADDITIONAL INFORMATION:	