

S E R V I C E N O T E

SUPERSEDES: None

85462A EMC Receiver RF Section

Serial Numbers: 0000A00000 / 9999Z99999

EEROM Firmware Upgrade

Duplicate Service Notes: 85422E-04, 85462A-04

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Qty.	Description
85462-60044	1	Firmware Kit

Situation:

Replacement firmware corrects discrepancy between peak, quasi-peak, and average detector values when making a stepped measurement of a CW signal.

Solution/Action:

At the customer's request or when returned to the CSC for repair or calibration, if the firmware revision date is not Rev 95.11.21, then order kit 85462-60044. Also order new Reference Manual, 5962-5084 if replacing firmware version Rev. 94.02.02.

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☒ AGREEABLE TIME	STANDARDS: Labor 0.5 Hour	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: Product's Support Life
AUTHOR: ATB	ENTITY: 5340	ADDITIONAL INFORMATION:	