S E R V I C E N O T E

SUPERSEDES: NONE

85462A EMC Receiver RF Section

Serial Numbers: 0000A00000 / 9999Z99999

EPROM Firmware Upgrade

Duplicate Service Notes: 85422E-06

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description

85462-60047 Firmware Kit

Situation:

Replacement firmware will correct the quasi-peak noise floor value in the stepped measurement mode. It will also improve the 200 Hz CISPR filter mask centering technique, as well as, improve the quasi-peak and average hardkey auto-range.

Solution/Action:

The firmware shall be replaced with p/n 85462-60047 upon customer request, or when returned to the CSC for repair or calibration. If the firmware revision data is not 96.10.18, then order kit 85462-60047.

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ■ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: January 1998
AUTHOR: JS	ENTITY: 5340	ADDITIONAL INFORMATION:

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

