|   | S                                | Е  | R      | V   | I | С                              | Е | Ν            | 0    | Т         | Е |
|---|----------------------------------|--|--------|-----|---|--------------------------------|---|--------------|------|-----------|---|
| SUPERSEDES: None<br>8564E Option 042 Portable Spectrum Analyzer |                                  |  |        |     |   |                                |   |              |      |           |   |
| Possible Shoulder Strap Failure Under Load                      |                                  |  |        |     |   |                                |   |              |      |           |   |
|   |                                  |  |        | POS |   | /ARN<br>e perso                |   | JURY         |      |           |   |
| POSSIBLE PERSONAL INJURY<br>Serial Numbers: See Below           |                                  |  |        |     |   |                                |   |              |      |           |   |
|   | Duplicate Service Notes:         |  |        |     |   |                                |   |              |      |           |   |
|   | 8561]<br>8562]<br>8563]<br>8564] | 8560E-18-S 8560E/042 Serial Numbers: 3517A01927/3804A03382   8561E-14-S 8561E/042 Serial Numbers: 3517A01242/3804A02191   8562E-06-S 8562E/042 Serial Numbers: 0000A00000/3751A00632   8563E-18-S 8563E/042 Serial Numbers: 3517A0194/3804A08329   8564E-12-S 8564E/042 Serial Numbers: 3551A00394/3751A01087   8565E-12-S 8564E/042 Serial Numbers: 3551A00369/e751A00852 |        |     |   |                                |   |              |      |           |   |
|   |                                  |  |        |     |   |                                |   |              |      | Continued | d |
|   |                                  |  |        |     |   |                                |   | DATE: August | 1998 |           |   |
| ADMI NISTRATI VE INFORMATIO N                                   |                                  |  |        |     |   |                                |   |              |      |           |   |
| SERVICE NOTE CLASSIFICATIO N:<br>PRIORITY SAFETY                |                                  |  |        |     |   |                                |   |              |      |           |   |
| ACTION<br>CATEGORY: IMMED                                       |                                  |  | DIATEI | _Y  | S | STANDARDS:<br>LABOR - See Text |   |              |      |           |   |

LOCATION ON-SITE SERVICE RETURN USED RETURN CATEGORY: See Text □ SERVICE CENTER SCRAP INVENT ORY: PARTS: SCRAP SEETEXT SEETEXT AGILENT RESPONSIBLE UNTIL: ALWAYS AVAILABILITY: ALWAYS AUTHOR:GPB ADDITIONAL INFORMATION: None ENTIT Y:5320

© 1998 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



8564E-12-S

## To Be Performed By: Agilent-Qualified Personnel, Customer

## **Parts Required:**

| P/N       | Description        | Quantity |
|-----------|--------------------|----------|
| 1540-1130 | Soft Carrying Case | 1        |

## Situation:

Agilent has learned that the stitching which fastens the shoulder strap to the bag on some soft carrying cases may fail the load test (four times the intended mass). Failure of the stitching can result in damage to the instrument and possibly personal injury.

## **Solution / Action:**

The carrying case which came with option 042 instruments in the serial ranges called out should be sent back to Agilent for exchange. New cases will be supplied under warranty. This exchange also applies to 1540- 1130 Carrying Cases purchased separately from Agilent during the 1997 calendar year. Customers may arrange to have their cases exchanged by contacting the Microwave Instruments Division Spectrum Analyzer Support Line at (707) 577-6801.