DAYTON

HALLIWELL BERNARD J

8568A-37

SERVICE NOTE

Supersedes:

None

HP MODEL 8568A SPECTRUM ANALYZER

All Serial Prefixes

RF ATTENUATOR WITH CALIBRATION ROM REPLACEMENT

This service note documents the replacement of the attenuator calibration ROM when replacing the RF Attenuator in all 8568A Spectrum Analyzers.

When either a new attenuator (HP Part Number 08568-60118) or a restored attenuator (HP Part Number 08568-60117) is ordered a calibration ROM is shipped with the attenuator. This ROM contains the characteristics for that particular attenuator and provides the means to achieve the specified amplitude accuracy. Because each attenuator is individually characterized replacement ROMs are not separately available.

The ROM included with the attenuator should be installed on the A12 RF Section Interface Assembly replacing A12U17.

RO/mfe/WN

8/80-45



FOR MORE INFORMATION, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE or East (201) 265-5000 Midwest (312) 255-9800 South (404) 955-1500 West (213) 970-7500 or (415) 968-9200; OR WRITE, Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. IN EUROPE, CALL YOUR LOCAL HP SALES or SERVICE OFFICE OR WRITE, Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box, CH-1217 MEYRIN 2 - Geneva, Switzerland. IN JAPAN, Yokogawa-Hewlett-Packard Ltd., 9-1, Takakura-cho, Hachioji-shi, Tokyo, Japan 192.