

**86146B-02**

**S E R V I C E                      N O T E**

---

Supersedes:  
NONE

**86146B Optical Spectrum Analyzer**

**Serial Numbers: DE44103086 / DE99999999**

**Random restart of OSA application when pressing 'Local' button twice**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
n/a		

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b>	
AUTHOR: jm	PRODUCT LINE: 3E
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008  
PRINTED IN U.S.A.

**May 9, 2008**  
Rev. 14



**Situation:**

In very seldom cases when pressing the local button twice quickly on a running optical spectrum analyzer the OSA application restarts by itself. After the application restart the instrument has full measurement capability. In very seldom cases the OSA application is also restarted when pressing the local button once.

**Solution/Action:**

Avoid pressing the local button twice quickly.

In case the OSA shows the above described behaviour wait until the OSA application has finished the restart.