87104B-02A

S E R V I C E N O T E

Supersedes: 87104B-02

Repair Strategy for Americas Skyworks Mexico's return units

Serial Numbers:

All return units from Skyworks.

Shorten the TAT of reported units send back to factory for further Failure Analysis

Parts Required:

P/N Description

87104-60058 EM Switch, Multiport, SP4T, DC-20GHz, Terminated

Opt 161-T24, PB Free

Situation:

Customer claims that 8% of 87104B in their application are failed. We wish to have shorter TAT return of all the claims units back to factory (F03) for further failure analysis.

Revision History:

110 (1510H 111500H) (
	Revision Number	Date	Author	Reason For Change
	1.0	1/16/2014	YC Sin	As published
	2.0	3/3/2014	YC Sin	Revised process flow in Solution/Action

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

INTERNAL ONLY DOCUMENT

[x] Calibration NOT Required PRODUCT LINE: PLWN
AUTHOR: YCSin

ADDITIONAL INFORMATION: For customer satisfaction, wish to have fast TAT for all claim units return to factory for further FA.

© AGILENT TECHNOLOGIES, INC. 2014 PRINTED IN U.S.A.




March 4, 2014

Rev. 21

Page 2 of 2 87104B-02A

Solution/Action:

1. For customer satisfaction, SSU created new process of "SPO Americas Skyworks Mexico Dedicated Inventory" to speed up the process of replacement units to customer. Refer in below process:



2. Once reported units received in SPO Roseville, PRP process apply to ship unit back to F03 for failure analysis.

February 10, 2014