

# 87106B-02A

## S E R V I C E N O T E

Supersedes  
87106B-02

87106B - Switch, SP6T, DC-20 GHz, terminated

**Serial Numbers:**

All return units from Skyworks.

**Shorten the TAT of reported units sent back to factory from Americas Skyworks Mexico for further Failure Analysis**

**Parts Required:**

P/N	Description
87106-60079	EM Switch, Multiport, SP6T, DC-20GHz, Terminated Opt 161-T24, PB Free

**Situation:**

Customer claims that 8% of **87106B** in their application are failed. We wish to have shorter TAT return of all the claims units back to factory (F03) for further failure analysis.

**Revision History:**


Revision Number	Date	Author	Reason For Change
1.0	1/16/2014	YC Sin	As published
2.0	3/3/2014	YC Sin	Revised process flow in Solution/Action

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b> <b>INTERNAL ONLY DOCUMENT</b>	
X Calibration NOT Required	PRODUCT LINE: PLWN AUTHOR: YCSin
ADDITIONAL INFORMATION: For customer satisfaction, wish to have fast TAT for all claim units return to factory for further FA.	

**Solution/Action:**

1. For customer satisfaction, SSU created new process of “SPO Americas Skyworks Mexico Dedicated Inventory” to speed up the process of replacement units to customer. Refer in below process:



Agilent Restricted  
February 10, 2014

2. Once reported units received in SPO Roseville, PRP process apply to ship unit back to F03 for failure analysis.