

S E R V I C E N O T E

SUPERSEDES: None

89410A Vector Signal analyzer

Serial Numbers: 0000A00000 / 3313A00177

New analog motherboard improves channel match**Duplicate Service Notes:**

89410A-02

89440A-02

To Be Performed By: Agilent-Qualified Personnel**Parts Required:**

Part No.	Description
89410-66591	A91 Analog Motherboard

Equipment Required:

Motherboard Cable extraction tool, p/n 8710-2050

This tool is included in the 89410A Service kit, p/n 89410-84401.

Situation:

The analyzer may fail the channel match specification. A clock line on the A91 Analog Motherboard needs to be isolated from other signal lines.

Solution/Action:

Install a new A91 Analog Motherboard assembly. See Replacing Assemblies in the 89410A Service Guide.

DATE: 02 April 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☒ AGREEABLE TIME	STANDARDS: Labor 2.0 hrs	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: 02 April 1995
AUTHOR: CMG	ENTITY: A100	ADDITIONAL INFORMATION:	

