

S E R V I C E N O T E

SUPERSEDES: None

89410A Vector Signal Analyzer

Serial Numbers: 0000A00000 / 3320A00267

External DIN keyboard failure caused by analyzer's slow power up.

Duplicate Service Notes: 89440A-04

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Description
89410-66580	Keyboard

Situation:

External DIN keyboards may not function properly even though there is power to the analyzer's DIN connector. Here are the possible symptoms:

- External keyboard does not appear to be sending scan codes to the analyzer.
- Analyzer's keyboard LEDs flash on and off and the analyzer operates extremely slow.

Solution/Action:

Install a new A80 Keyboard assembly, revision B or greater. See Replacing Assemblies in the 89410A Service Guide.

DATE: 10 August 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☒ AGREEABLE TIME	STANDARDS: Labor 1.5 hrs	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: 10 August 1995
AUTHOR: CMG	ENTITY: A100	ADDITIONAL INFORMATION:	