

S E R V I C E N O T E

SUPERSEDES: None

89430A RF Section**Serial Numbers:** 0000A00000/9999Z99999**Installation kit required when replacing A50 YIG assembly****Situation:**

A new YIG assembly has been designed for the 89430A. New brackets must be installed for mounting the new YIG assembly.

Solution/Action:

When replacing an older style YIG assembly, recognized by the rectangular shape, order part number 89430-67552. This part number includes the new YIG assembly, brackets and an installation note.

When replacing a newer style YIG assembly, recognized by the round shape, order part number 89430-67551. This is the part number for the YIG assembly only.

DATE: September 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

DWH

ENTITY:

A100

ADDITIONAL INFORMATION:

CO A100-9904127

