B2961B-01

Modification Recommended Service Note

Supersedes: NONE

B2961B 6.5 Digit Low Noise Power Source, 32W, 210V, 3A, 1ch

Serial Numbers:

See table below.

The Problem

The LAN MAC address assigned to B2961B may have a duplicate with the one assigned to 33502A.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

| ACTION CATEGORY: | [[]] ON SPECIFIED FAILURE X AGREEABLE TIME | STANDARDS LABOR: 1.0 Hours | | |
|---|---|---|--|--|
| LOCATION CATEGORY: | [[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) X SERVICE CENTER [[]] CHANNEL PARTNERS | SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP X SEE TEXT X SEE TEXT | | |
| AVAILABILITY: PRODUCT'S SUPPORT LIFE | | NO CHARGE AVAILABLE UNTIL: Dec 31, 2022 | | |
| [[]] Calibration Required X Calibration NOT Required | | PRODUCT LINE: 1H AUTHOR: HT | | |

ADDITIONAL INFORMATION:



Situation:

If B2961B is connected to the same LAN with 33502A, there may be a conflict and may cause issues related to LAN communication.

Solution/Action:

Send the B2961B to the Keysight Service Center for changing the LAN MAC address to a unique number that will not have the conflict with other equipment.

Affected Instruments:

The instruments with the serial number listed below is confirmed to be affected:

MY60440107

Revision History:

| Date | Service Note Revision | Author | Reason for Change |
|-------------|-----------------------------|----------------|-------------------|
| 10 Nov 2021 | 01 | Hiro Tsunemoto | As Published |
| | | | |