

DSO80204B-05

S E R V I C E N O T E

Supersedes:
NONE

2GHZ 4 Ch Infiniium Oscilloscope

Serial Numbers: MY46001401 and above, SG46001401 and above.

The purpose of this Service Note is to notify service personal that the original CPU PCA assembly has been replaced in these affected units. This new assembly is not backward compatible; therefore the following parts were also changed in order to work with the new CPU PCA assembly.

This service note is an addendum to the Service Guide until it is revised.

Parts Required:

P/N	Description	Qty.
0960-2689	ADLink M880 motherboard w/ 2 SATA cables	1
3160-4243	Heatsink/Fan assembly	1
D8104-60103	Motherboard deck w/ 4 mount points for heatsink/fan	1
D8104-61606	Power Cable	1
D8104-61607	Backlight cable	1
D8104-61608	Front panel USB port	1
D8104-61609	Touchscreen USB cable	1
54855-61628	Motherboard switch cable	1
1400-2120	ADD2 board replaced by rear panel slot filler plate	1
0515-0430	Screw for ADD2 or filler plate	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: MR PRODUCT LINE: PL1A
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



July 16, 2007

Situation:

When using Service Manual D8104-97006 it does not list the appropriate part number for service.

Solution/Action:

Reference:

Old	New	Description
81004-68809	0960-2689	ADLink M880 motherboard w/ 2 SATA cables
NA	3160-4243	Heatsink/Fan assembly
D8104-60102	D8104-60103	Motherboard deck w/ 4 mount points for heatsink/fan
D8104-61605	D8104-61607	Backlight cable
D8104-61601	D8104-61606	Pyramid power cable
D8104-61602	D8104-61608	Front panel USB port
D8104-61604	D8104-61609	Touchscreen USB cable
54855-61624	54855-61628	Motherboard switch cable
0960-2530	1400-2120	ADD2 board replaced by rear panel slot filler plate
0515-0430	0515-0430	Screw for ADD2 or filler plate