DS09104A-08

# Information Only Service Note

Supersedes: NONE

# DSO9104A - Infiniium DSO, 1GHz, 10/20 GSa/s, 4Ch

Serial Numbers: ALL

Upon completion of service or user calibration if the customer is not ok with upgrading the revision of software of the scope to >5.50.0033, there is a chance that the unit may end up with excessive noise on the screen at certain vertical settings.

## Parts Required:

P/N Description Qty.

NONE

#### ADMINISTRATIVE INFORMATION

[[]] Calibration Required
[X] Calibration NOT Required

PRODUCT LINE: PL-1A AUTHOR: EG


ADDITIONAL INFORMATION:



## Situation:

- 1. Noise appears all over the screen after performing service/user calibration.
- 2. The noise on full screen could happen on any channel in 50 Ohm impedance on certain vertical settings. Some instances occurs at 200mV/div and not on other settings, whereas some occur at 10mV/div and not on other settings.

Here are some screenshots of the issue:





# Solution/Action:

Install revision of software 5.50.0033 or higher.

# Revision History:

ion	Reason for Change	
Ed Gorbea	As Published	
İ	ion Ed Gorbea	