DS09404A-08

# Information Only Service Note

Supersedes: NONE

DSO9404A - Infiniium DSO, 4GHz, 10/20 GSa/s, 4Ch

Serial Numbers: ALL

Upon completion of service or user calibration if the customer is not ok with upgrading the revision of software of the scope to >5.50.0033, there is a chance that the unit may end up with excessive noise on the screen at certain vertical settings.

# Parts Required:

P/N Description Qty.

NONE

### ADMINISTRATIVE INFORMATION

[]] Calibration Required
[X] Calibration NOT Required

PRODUCT LINE: PL-1A

AUTHOR: EG


ADDITIONAL INFORMATION:



### Situation:

- 1. Noise appears all over the screen after performing service/user calibration.
- 2. The noise on full screen could happen on any channel in 50 Ohm impedance on certain vertical settings. Some instances occurs at 200mV/div and not on other settings, whereas some occur at 10mV/div and not on other settings.

Here are some screenshots of the issue:





## Solution/Action:

Install revision of software 5.50.0033 or higher.

# Revision History:

rte Author vision	Reason for Change	
Ed Gorbea	As Published	
		vision