

S E R V I C E N O T E

SUPERSEDES: NONE

E3102A: 4073A Ultra Advanced Parametric Tester

Serial Numbers:

- E3101A JP10D00101/JP30D00577
- E3101K JP10E90101/JP10E90103
- E3102A JP10G20101/JP20G20242
- E3102L JP10H90101/JP10H90113
- E3103A JP10H30101/JP10H30118

Display picture may be distorted.

Duplicate Service Notes: E3101A-14, E3102A-02, E3103A-01

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Description	Quantity
E3120-61687	VGA Video Ext Cable	1

Situation:

When you use tester controller (E3170A/E3171A/E3172A) with the video extension cable (E3120-61677), display picture may be distorted.

Solution / Action:

This is caused by noise through the VGA extension cable. Replace the video extension cable with E3120-61687.

DATE: December 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: December 2002		
AUTHOR: SY	ENTITY: 3300		ADDITIONAL INFORMATION:		

