

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

E3630A-04

S E R V I C E N O T E

Supersedes: NONE

E3630A DC Power Supply

Serial Numbers: KR0000001 through KR09999999, MY4000001 through MY40008500, SG4000001 through SG40005000

The Grey key caps (P/N E3630-40007) may crack overtime.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
E3630-40007	Key Cap	3

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.1 Hours	
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE X SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN X SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN X SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Always.	
AUTHOR: BK	PRODUCT LINE: WC		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



August 29, 2005

Situation:

The key caps (P/N E3630-40007) used on the front panel of the E3630A may potentially crack over time due to a material issue.

Solution/Action:

New material has been introduced to replace the existing material used to mold the key caps. Replace all the key caps assembled on the instrument with the new ones.