MODIFICATION RECOMMENDED

E4419B-23

S E R V I C E N O T E

Supersedes: NONE

E4419B EPM-441A Single/Dual Channel Power Meter

Serial Numbers: GB43312958, GB43312959, MY40510530, MY45104261, MY50000468

Calibrations performed on some Single/Dual-Channel Power Meters by Agilent Technologies between February 6^{th} , 2012 and February 6^{th} , 2014 show a pass in the OUTPUT SWR; OUTPUT SWR(REAR PANEL) test, even if the SWR value is < 1.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION [[]] ON SPECIFIED FAILURE CATEGORY: X AGREEABLE TIME	STANDARDS LABOR: 1.0 Hours			
LOCATION [[]] CUSTOMER INSTALLABLE CATEGORY: [[]] ON-SITE (active On-site contract required) X SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE X RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT USED [[]] RETURN PARTS: [[]] SCRAP [[]] SEE TEXT			
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 7-February-2015			
X Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: TJ AUTHOR: MW			
ADDITIONAL INFORMATION: Gratis Support need to be chosen as the billing type, while cre	eating the customer order.			

© AGILENT TECHNOLOGIES, INC. 2014 PRINTED IN U.S.A.



February 25, 2014

Rev. 22

Page 2 of 2 E4419B-23

Situation:

The Quality issue is caused by a Test-Software defect which caused a False Pass judgment. Agilent corrected the Power Meter Test Software and installed it on all Test Systems by February 14th, 2014.

Solution/Action:

- 1. Agilent will send a customer letter to all affected customers.
- 2. Customer, please contact nearest Agilent Customer Care Center and send instrument to Agilent for free calibration.
- 3. Agilent WCSS Service & Support to calibrate affected products at Agilent's expense.
- 4. After re-calibration Agilent to send the instrument back to the customer.

Revision History:

revision mistory:				
	Revision	Date	Author	Reason For Change
	Number			
	1.0	14 th Feb 2014	MW	As published