MODIFICATION RECOMMENDED

E4990A-01

S E R V I C E N O T E

Supersedes: NONE

E4990A Impedance Analyzer

Serial Numbers: MY54100101 to MY54100334, MY54100336 to MY54100359, MY54100364, MY54100366, MY54100367, SG54100101 to SG54100108

Incorrect data in touchstone file (S1P file)

Parts Required:		
P/N	Description	Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION [[]] ON SPECIFIED FAILURE CATEGORY: [X] AGREEABLE TIME	STANDARDS LABOR: 0.0 Hours				
LOCATION [X] CUSTOMER INSTALLABLE CATEGORY: [[]] ON-SITE (active On-site contract required) [[]] SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED [[]] RETURN PARTS: [[]] SCRAP [[]] SEE TEXT			
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTI	L: 01-Mar-2017			
[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: WN AUTHOR: KW				
ADDITIONAL INFORMATION:					

© Keysight Technologies 2015 Printed in U.S.A.



Page 2 of 2 E4990A-01

Situation:

When using the following steps to save trace data of S-parameter in Touchstone format, FW which is below A.02.01 saves incorrect data to a touchstone format file (S1P file).

- 1. Press Channel Next (or Channel Prev) and Trace Next (or Trace prev) to select the trace to be saved.
- 2. Press Save/Recall > Save S1P > S1P Format.
- 3. Click the softkey that corresponds to the data format you want to save.
- 4. Click Save S1P

Solution/Action:

Update the firmware to A.02.01 or later.

Revision History:

	vice Note Revision	Date	Author	Reason For Change
E	1990A-01	04Mar2015	KW	As published