

E4991B-09

Information Only Service Note

Supersedes:
NONE

E4991B Impedance Analyzer, 1MHz to 500 MHz/1 GHz/3 GHz

Serial Numbers: ALL

Manufacturing ID Number: N/A

Firmware Update to Fix Diagnostic Test Z Measurement Open/Short Fail.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: WN
AUTHOR: BS

ADDITIONAL INFORMATION:

Situation:

The E4991B unit with firmware A.01.15 and below may cause E4991B's Diagnostic Test to fail on Z Measurement Open and Short. This is due to the Diagnostic Test does not clear off the adapter setting upon performing the diagnostic test.

Solution/Action:

Update E4991B's firmware to A.01.16.

Revision History:

Date	Service Note Revision	Author	Reason for Change
10 Apr 2017	01	BS	As Published