Information Only Service Note

Supersedes: NONE

E5055A SSA-X Signal Source Analyzer, 1 MHz to 8 GHz

Serial Numbers: ALL

Manufacturing ID Number: N/A

How to handle optional licenses which customers purchased in return to factory (RTF) process

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: WN
X Calibration NOT Required AUTHOR: YK

ADDITIONAL INFORMATION:



Situation:

In a case of RTF, optional licenses which a customer purchased are not installed on a unit when the unit is returned from the factory to service centers. The reason is that the production team don't have permission to check the customer's licenses.

Solution/Action:

Service centers need to install them after receiving the unit from the factory or ask customers to install them due to avoid confusing the customer.

Compare difference of licenses between Keysight License Manager (KLM) on the unit and Keysight Software Manager (KSM). If you find missing licenses, get the licenses from KSM and install them on the unit by KLM. See Figures 1 to 3 for your reference about KSM 7.4 operation. You can refer to Solid State Drive Kit's manual (E5054-90101) for how to install licenses by KLM.




Fig. 2 Search hosts with S/N




Fig. 3 License file is available

Revision History:

Date	Service Note Revision	Author	Reason for Change
17 Feb 2023	01	YK	As Published