SERVICE

E5061B-03

Supersedes: None

E5061B 5Hz to 3GHz Network Analyzer

Serial Numbers: ALL

E5061B Diagnostic Receiver IF Ranging Test Procedure

Parts Required:

P/N Description Qty.

None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: LS	PRODUCT LINE: WN
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010 PRINTED IN U.S.A.



Page 1 of 2

July 14, 2010

Page 2 of 2 E5061B-03

Situation:

This service note describes how to correctly run the Receiver IF Ranging test in the Diagnostic.vba test. Previously, when service center runs this test, it has intermittent failure at the R1 and R2 10MHz point. Thus, service center can run this test with the temporary following procedure to eliminate the bug which was found in the Diagnostic.vba test until the new FW is released.

Solution/Action:

- 1. Run the E5061B Diagnostic.vba test.
- 2. Go to the Main Menu and select the Receiver IF Ranging Test.
- 3. Select only the R1&T1 test and execute the test.
- 4. Go back to Main Menu
- 5. Select only the R2&T2 test and execute the test.