

E5063A-01

S E R V I C E N O T E

Supersedes:
NONE

E5063A ENA series network analyzer

Serial Numbers: MY54100001 to MY54100130

Failed to Initializing DSP error

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required	PRODUCT LINE: WN
<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR: jm
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2014
PRINTED IN U.S.A.

February 4, 2014


Rev. 21



Agilent Technologies

Situation:

You might see “Hardware error; Failed to Initializing DSP” at the left bottom of the screen while booting up the instrument, if the firmware revision is A.01.01.



Solution/Action:

Update the firmware to A.01.02 or later.

Revision History:

Revision Number	Date	Author	Reason For Change
E5063A-01	3-Feb-2014	jm	As published