

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E5070B-04

S E R V I C E N O T E

Supersedes:
None

E5070B ENA Series Network Analyzer, 300 kHz to 3 GHz

Serial Numbers: See Solution/Action

GPIB card assembly (A24) part number change

Parts Required: See Solution/Action

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DK PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



January 9, 2004

Situation:

E5070B's GPIB assembly (A24 GPIB CARD) was changed from 82350I to E5070-61007 because a 82350I GPIB card had been obsolete. To adapt this change, a main chassis is changed from E5071-60021 to E5070-60023, and the old chassis E5071-60021 requires 82350I for GPIB repair. Thus Agilent prepared 5185-3792 as a life time buy part of 82350I for E5071-60021 chassis.

The equipments those serial numbers are JP1KKxxxxxx, and MY42100210 and below use E5071-60021 chassis, thus these units need 5185-3792 for their A24 GPIB CARD repair.

Solution/Action:

For serial number JP1KKxxxxxx and MY42100210 and below use the following part instead of 82350I.

P/N	Description	Qty.
5185-3792	82350I for ENA Support high-performance PCI GPIB card	1

For serial number MY42100211 and above use the following part instead of 82350I.

P/N	Description	Qty.
E5070-61007	PCI GPIB assy, general purpose	1

Retrofit Time

Assembly Time: No additional time due to this service note.
 Adjustment Time: No additional time due to this service note.
 Performance Tests Time: No additional time due to this service note.
 Total Time: No additional time due to this service note.