EE071D 10E

Information Only Service Note

Supersedes: E5071B-12D

E5071B RF Network Analyzer, 300 kHz to 8.5 Ghz

Serial Numbers: ALL

New Parts to perform attenuator upgrade have become unavailable. Refurbished parts are now available

Parts Required:

P/N Description Qty.
5188-9406 Refurbished Step Attenuator Programmable , Exch 1
33321-69068 Refurbished Attenuator Programmable 35dB 12GHz , Exch 1

ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: WN X Calibration NOT Required AUTHOR: EB

ADDITIONAL INFORMATION:



Situation:

Parts to perform attenuator upgrade have become unavailable. Refurbished attenuators are now available to replace failed attenuators.

Solution/Action:

When the E5071B Internal Test fails at Step Attenuator Test Group, replace the old attenuator based on the part number of the currently installed attenuator as follows:

_Currently installed: Replace with:

 33321-60059
 5188-9406

 33321-60068
 33321-69068

Revision History:

10 Jul 2017 05 Fric Baker As Published	Date	Service Note Revision	Author	Reason for Change
10 0 01 2017	10 Jul 2017	05	Eric Baker	As Published