

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

E6393A-01

S E R V I C E N O T E

Supersedes:
None

Agilent Technologies E6393A CDMA MS Test Set

Serial Numbers: JP1MJ00101/JP1MJ00207

Firmware Rev A.01.12 has a problem in RFCH handoff.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
Agilent 34398A	RS-232 Cable Kit	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AGILENT RESPONSIBLE UNTIL: end of product support life			
AUTHOR: SA		PRODUCT LINE: BJ	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



January 17, 2002

Situation:

E6393A firmware revision A.01.12 has a following problem.

RFCH handoff always fails after PRESET (or *RST remote command) if destination RFCH is the same as the last RFCH handoff.

Solution/Action:

Upgrade the E6393A firmware to Rev A.01.13 or later by using PC download program. PC download program can be obtained from Agilent web site. follow the instruction below.

1. Go to <http://www.agilent.com>
2. Enter the key word E6393A in the quick search box and click “go”.
3. Click the link to the “E6393A Firmware Upgrade”
4. In this “E6393A Firmware Upgrade” page, you can down load the “PC download” program and the latest firmware file. Follow the instruction described in this page.