

Modification Recommended Service Note

Supersedes:
NONE

E6464AC16 Multi transceiver RF test set 16 TRX channels

Serial Numbers: FI64223063

The Problem – Certain units with Rev 007 PC module or earlier can experience boot up issues due to DC/DC converter revision installed.

Parts Required:

P/N	Description	Qty.
F8800-61709	Levi module	1

ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	<input checked="" type="checkbox"/> AGREEABLE TIME	LABOR:	1.0 Hours
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE (No Parts involved) <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE:	<input checked="" type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (<i>active On-site contract required</i>) <input type="checkbox"/> CHANNEL PARTNERS	INVENTORY:	<input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
USED		PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	Nov 1 st 2027
	<input checked="" type="checkbox"/> Calibration Required <input type="checkbox"/> Calibration NOT Required	PRODUCT LINE:	DI
		AUTHOR:	AA

ADDITIONAL INFORMATION:

Situation:

A subset of units with PC module revision 007 or earlier need to have the PC module replaced due to potential boot issues seen on the units.

Solution/Action:

The risk of failure is low but on the next service event Keysight will proceed to replace the PC module within the unit under this service note

Revision History:

Date	Service Note Revision	Author	Reason for Change
22 October 2024	01	Andrew Alford	As Published