

E6640A-02

# Information Only Service Note

Supersedes:  
[ NONE ]

## E6640A - EXM Wireless test set

Serial Numbers: ALL

Manufacturing ID Number M9300A reference modules with manufacturing ID numbers greater than 1E5743xxxx

**The Problem** – M9300A reference modules with manufacturing ID numbers greater than 1E5743xxxx used in EXM repairs requires and instrument Software update to E.19

### Parts Required:

[NONE]

### ADMINISTRATIVE INFORMATION

---

X Calibration Required

PRODUCT LINE: PL13

Calibration NOT Required    Calibration NOT Required

AUTHOR: MJW

---

ADDITIONAL INFORMATION:

---

**Situation:**

M9300A reference modules with manufacturing ID numbers less than 1E5743xxxx used Xilinx Flash memory. Due to a part update to Micron Flash memory required a FPGA update. This caused EXM instrument repairs which require new M9300A Reference assembly with manufacturing ID numbers **greater** than 1E5743xxxx to update the instrument Software to E.19.71 or greater to have the assembly work properly.

**Solution/Action:**

EXM instrument repairs which require a new M9300A Reference assembly with manufacturing ID numbers **greater** than 1E5743xxxx are required to perform an instrument Software update to E.19.71 or greater to work properly with the new flash memory on the M9300A Module.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
12 June 2018	01	Michael Woichik	As Published