

E6640A-03

# Information Only Service Note

Supersedes:  
NONE

## E6640A - EXM Wireless test set

Serial Numbers: ALL

**The Problem** – M9430A and M9431A modules are no longer manufactured. These have been replaced by the M9432A and M9433A modules

### Parts Required:

M9432-61802 - Replacement 2FD/2HD TRX module for M9430A

M9433-61802 - Replacement 4FD TRX module for M9431A

### ADMINISTRATIVE INFORMATION

---

Calibration Required  
X Calibration NOT Required

PRODUCT LINE: PL13  
AUTHOR: MJW

---

ADDITIONAL INFORMATION:

---

Situation:

The M9430A and M9431A modules are no longer manufactured. E6640A instruments that have these modules installed which require a TRX module replacement must first attempt to order the exchange assembly (69801) if the exchange part is not available.

Repairs need to use:

M9432-61802 - Replacement 2FD/2HD TRX module for M9430A

M9433-61802 - Replacement 4FD TRX module for M9431A

Solution/Action:

The M9432-61802 / M9433-61802 parts come as the replacement for a defective M9430A / M9431A module when the exchange assembly is not available.

These replacement M9432A / M9433A modules come with the options 504 and B40 already installed.

The module also has a serial number written into it.

A serial number overwrite is **NOT** performed on these modules.

If the module being replaced has different hardware option from 504 and B40, you must contact CSG support for the upgrade license.

**Siebel entitlement will but updated during the Unit Exchange process at the service center.**

Revision History:

Date	Service Note Revision	Author	Reason for Change
24 August 2018	01	Michael Woichik	As Published